



Adkins Energy LLC
P.O. Box 227
4350 W. Galena Road
Lena, IL 61048
Phone: (815) 369-9173
Fax: (815) 369-2043

www.adkinsenergy.com



July 16, 2021

Illinois Environmental Protection Agency
Division of Air Pollution Control
Compliance Enforcement Section (#40)
P.O. Box 19276
Springfield, IL 62794
Phone (217) 782-2113
Certified Mail No: 7018 3090 0001 6035 8708
(Two Copies)

Illinois Environmental Protection Agency
412 SW Washington St., Suite D
Peoria, IL 61602
Phone (309) 693-5463
Certified Mail No: 7018 3090 0001 6035 8715
(One Copy)

**RE: Semi-Annual Compliance Report – Subpart VV
Adkins Energy, LLC
4350 West Galena Road
Lena, IL 61048
Site ID No: 177802AAA
FESOP Permit No: 03060057**

Dear Sir/Madam:

Please find enclosed two (2) copies of the semi-annual compliance report for the first six months (January through June) of 2021, provided by Montrose. This report is being submitted pursuant to 40 CFR 60.487 (c) and Special Condition 2.9.10 (a) of the facility's FESOP Permit.

If you have any questions or need any additional information, please do not hesitate to contact me at 815-369-9173.

Sincerely,

Christopher L. Posey, CHMM, ASP
Environmental and Safety Manager

Enclosure

Semi Annual Summary

Reporting Period: Jan 1, 2021 to Jun 30, 2021

Units: PLANT

Areas: All

Regulations: NSPS-W

Rules: All

Services: All

Component Main Types: Pump and Valve

Component Sub Types: All

Include Visuals: No

Unit: PLANT

| | Beginning Count | Jan 1, 2021 to Jan 31, 2021 | Feb 1, 2021 to Feb 28, 2021 | Mar 1, 2021 to Mar 31, 2021 | Apr 1, 2021 to Apr 30, 2021 | May 1, 2021 to May 31, 2021 | Jun 1, 2021 to Jun 30, 2021 |
|-----------------------------------|-----------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| Pumps | 18 | 18 (94.44%) | 18 (94.44%) | 18 (94.44%) | 18 (94.44%) | 18 (94.44%) | 18 (94.44%) |
| Monitored | | 17 (94.44%) | 17 (94.44%) | 17 (94.44%) | 17 (94.44%) | 17 (94.44%) | 17 (94.44%) |
| Leaks Detected | | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) |
| Leaks Not Repaired within 15 Days | | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) |
| Valves | 326 | 326 (89.26%) | 326 (89.26%) | 326 (89.26%) | 326 (89.26%) | 326 (89.26%) | 326 (89.26%) |
| Monitored | | 291 (89.26%) | 291 (89.26%) | 291 (89.26%) | 291 (89.26%) | 291 (89.26%) | 291 (89.26%) |
| Leaks Detected | | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) |
| Leaks Not Repaired within 15 Days | | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) | 0 (0.00%) |



Summary

| | Beginning Count | Added | Removed | Ending Count | Components Monitored | Monitoring Events | Leaks | Not Repaired within 15 Days |
|--------------|-----------------|----------|----------|--------------|----------------------|-------------------|----------|-----------------------------|
| Pump | 18 | 0 | 0 | 18 | 17 | 102 | 0 | 0 |
| Valve | 326 | 0 | 0 | 326 | 322 | 613 | 0 | 0 |
| Total | 344 | 0 | 0 | 344 | 339 | 715 | 0 | 0 |