



**FOLLOW UP REPORT – FAX NOTIFICATION FORM**  
**Site Identification No. 177802AAA; FESOP Permit No. 03060057**

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048  
Phone 815-369-9173; Fax: 815-369-2043

**Fax to:** IEPA - Division of Air Pollution Control  
Compliance Enforcement Section (#40) - Springfield  
Fax: 217-782-6348 (Phone 217-782-2113) **Fax to:** IEPA Division of Air Pollution -Peoria Field Office  
309-693-5467 (Phone 309-693-5463)

**Date:** 4/21/11 **Time:** 8:30 a.m. **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

**Emission Unit:** Dryer & Distillation Scrubber

**Date:** 4/18/11 **Start Time:** 5:55 p.m. **Duration:** 3 minutes

**Description of Deviation:**  
Dryer went down on speed switch C-705 and air purge

**Effect of Deviation on Compliance:**  
Dryer vent went to atmosphere. The process scrubber was put online less than 2 minutes after the dryer shutdown.

**Estimate of Excess Emissions:**  
A follow up report will be sent that show the estimate of emissions.

**Cause of Deviation:**  
Dryer went down due losing the belts on feed conveyor C-705.

**Corrective Action or Preventive Action Taken:**  
The drive system for that conveyor has been upgraded to try and prevent similar issues with that conveyor.

Written Follow Up Report To Be Issued:  yes  no **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**