



FOLLOW UP REPORT – FAX NOTIFICATION FORM
Site Identification No. 177802AAA; FESOP Permit No. 03060057

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048
 Phone 815-369-9173; Fax: 815-369-2043

Fax to: IEPA - Division of Air Pollution Control
 Compliance Enforcement Section (#40) - Springfield
 Fax: 217-782-6348 (Phone 217-782-2113)

Fax to: IEPA Division of Air Pollution -Peoria Field Office
 309-693-5467 (Phone 309-693-5463)

Date: 12/1/11 **Time:** 9:00 am. **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

Emission Unit: Dryer

Date: 11/23/11 **Start Time:** 10:35 pm **Duration:**

Description of Deviation:
 C-702 kicked out causing fast shut down on the dryer. Distillation scrubber was put online in 4 minutes.

Effect of Deviation on Compliance:
 Dryer vent went to atmosphere before the outlet temperature reached 130 degrees.

Estimate of Excess Emissions:
 A report showing the estimated emissions from this event has been attached.

Cause of Deviation:
 C-702 kicked out .

Corrective Action or Preventive Action Taken:
 C-702 was tripped at the breaker. Follow up – the root cause was determined to be a failed gear box on the conveyor. Maintenance replaced the gearbox before the dryer could be restarted.

Written Follow Up Report To Be Issued: yes no **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**