



FOLLOW UP REPORT – FAX NOTIFICATION FORM
Site Identification No. 177802AAA; FESOP Permit No. 03060057

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048
 Phone 815-369-9173; Fax: 815-369-2043

Fax to: IEPA - Division of Air Pollution Control
 Compliance Enforcement Section (#40) - Springfield
 Fax: 217-782-6348 (Phone 217-782-2113) **Fax to:** IEPA Division of Air Pollution -Peoria Field Office
 309-693-5467 (Phone 309-693-5463)

Date: 2-28-11 **Time:** 10:30 am **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

Emission Unit: Dryer and Distillation Scrubber

Date: 2/18/11 **Start Time:** 10:55 am **Duration:** varied

Description of Deviation:
 At 10:55 am, the dryer shut down due to a fault on the RTO processor. Programming was being upgraded on the RTO when it faulted out causing the dryer to vent immediately to atmosphere. The distillation scrubber was valved into the RTO at the time of the event, and the scrubber was put online at 10:58 am.

Effect of Deviation on Compliance:
 The dryer vented to atmosphere before the outlet temperature was below 130 degrees.

Estimate of Excess Emissions:
 A report showing the estimated emissions from this event has been attached.

Cause of Deviation:
 Processor fault on the dryer RTO while programming changes were being made.

Corrective Action or Preventive Action Taken:
 The processor fault was cleared and the changes were made to the program before the RTO and dryer were restarted.

Written Follow Up Report To Be Issued: yes no **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**