



**FOLLOW UP REPORT – FAX NOTIFICATION FORM**  
**Site Identification No. 177802AAA; FESOP Permit No. 03060057**

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048  
 Phone 815-369-9173; Fax: 815-369-2043

**Fax to:** IEPA - Division of Air Pollution Control  
 Compliance Enforcement Section (#40) - Springfield  
 Fax: 217-782-6348 (Phone 217-782-2113)      **Fax to:** IEPA Division of Air Pollution -Peoria Field Office  
 309-693-5467 (Phone 309-693-5463)

**Date:** 1/21/11      **Time:** 7:00 am      **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

**Emission Unit:** Dryer

**Date:** 1/15/2011      **Start Time:** 5:04 am      **Duration:** 36 minutes

**Description of Deviation:**  
 At 5:04 am the dryer shut down again due to a blown fuse in the control panel, thus causing the dryer exhaust to immediately vent to the atmosphere.

**Effect of Deviation on Compliance:**  
 The dryer vented to atmosphere before the outlet temperature was below 130 degrees.

**Estimate of Excess Emissions:**  
 A follow up report will be sent with the estimated emissions from this event.

**Cause of Deviation:**  
 Blown fuse.

**Corrective Action or Preventive Action Taken:**  
 The fuse was replaced and a loose wire was found and tightened before the dryer was restarted.

Written Follow Up Report To Be Issued:  yes  no      **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**