



DEVIATION REPORT – FAX NOTIFICATION FORM
Site Identification No. 177802AAA; FESOP Permit No. 03060057

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048
 Phone 815-369-9173; Fax: 815-369-2043

Fax to: IEPA - Division of Air Pollution Control
 Compliance Enforcement Section (#40) - Springfield
 Fax: 217-782-6348 (Phone 217-782-2113)

Fax to: IEPA Division of Air Pollution -Peoria Field Office
 309-693-5467 (Phone 309-693-5463)

Date: 4/22/11 **Time:** 7:15 p.m. **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

Emission Unit: Dryer

Date: 4/22/11 **Start Time:** 6:21 pm **Duration:** 17 minutes

Description of Deviation:
 While starting the dryer after fall shutdown, the cooling drum plugged and shut down causing the dryer to vent to atmosphere. The distillation scrubber was already online at the time of the event.

Effect of Deviation on Compliance:
 Dryer vent went to atmosphere before the outlet temperature reached 130 degrees.

Estimate of Excess Emissions:
 A follow up report will be sent that show the estimate of emissions.

Cause of Deviation:
 While checking the motor during shutdown, it was wired up to run in reverse causing the drum to load up with product and fault out.

Corrective Action or Preventive Action Taken:
 The cooling drum motor was re-wired to run in the forward position before restarting the dryer.

Written Follow Up Report To Be Issued: yes no **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**