



FOLLOW UP REPORT – FAX NOTIFICATION FORM
Site Identification No. 177802AAA; FESOP Permit No. 03060057

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048
 Phone 815-369-9173; Fax: 815-369-2043

Fax to: IEPA - Division of Air Pollution Control
 Compliance Enforcement Section (#40) - Springfield
 Fax: 217-782-6348 (Phone 217-782-2113) **Fax to:** IEPA Division of Air Pollution -Peoria Field Office
 309-693-5467 (Phone 309-693-5463)

Date: 1-20-11 **Time:** 3:00 pm **Operator:** Jason Townsend

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

Emission Unit: Dryer

Date: 1/12/11 **Start Time:** 11:33 pm **Duration:** 2 hrs 57 minutes

Description of Deviation:
 At 11:33 pm, the dryer shut down due to a shut down of an auger and a high temperature alarm causing it to vent immediately to atmosphere.

Effect of Deviation on Compliance:
 The dryer vented to atmosphere before the outlet temperature was below 130 degrees.

Estimate of Excess Emissions:
 A follow up report will be sent with the estimated emissions from this event.

Cause of Deviation:
 High temperature alarm caused by a feed conveyor shutting down and stopping flow of feed to the drum.

Corrective Action or Preventive Action Taken:
 The conveyor was inspected before it was restarted.

Written Follow Up Report To Be Issued: yes no **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**