



**DEVIATION REPORT – FAX NOTIFICATION FORM**  
**Site Identification No. 177802AAA; FESOP Permit No. 03060057**

P.O. Box 227; 4350 West Galena Road; Lena, Illinois 61048  
 Phone 815-369-9173; Fax: 815-369-2043

IEPA - Division of Air Pollution  
 Control  
 Compliance Enforcement Section

IEPA Division of Air Pollution -Peoria

**Fax to:** (#40) - Springfield  
 Fax: 217-782-1875 (Phone 217-782-2113)

**Fax to:** Field Office  
 Fax: 309-671-3024 (Phone 309-693-5463)

**Date:** 8/2/19      **Time:** 9:30 AM      **Operator:** Chris Posey

Federally Enforceable State Operating Permit (FESOP) Condition 3.5 identifies the minimum information required for a deviation report. The information is presented below.

**Emission Unit:** Fermentation Scrubber & Dryer

**Date:** 7/29/19      **Start Time:** 1:00 pm      **Duration:** varied

**Description of Deviation:**

At approximately 1:00 pm, the plant lost all electrical power. Once the utility electric could be reconnected, water flow to the scrubber was restarted at approximately 3:00 pm.

**Effect of Deviation on Compliance:**

Loss of water flow to the fermentation scrubber and venting of the dryer to atmosphere before the outlet temperature reached 130 degrees. The distillation scrubber was put online before restarting the process.

**Estimate of Excess Emissions:**

An estimated emissions report will be included with a follow up report.

**Cause of Deviation:**

Loss of electrical power from the utility.

**Corrective Action or Preventive Action Taken:**

The power was restored as quickly as possible, and water flow was re-established to the scrubber at 3:00 pm. The turbine was also restarted to provide power to the plant.

Written Follow Up Report To Be Issued:  yes  no      **If you have any questions, please call the Adkins Plant Manager Jason Townsend at 815- 369-9173 ext.245.**