



Adkins Energy LLC
P.O. Box 227
4350 W. Galena Road
Lena, IL 61048
Phone: (815) 369-9173
Fax: (815) 369-2043

www.adkinsenergy.com

July 23, 2019

Illinois Environmental Protection Agency
Division of Air Pollution Control
Compliance Enforcement Section (#40)
P.O. Box 19276
Springfield, IL 62794
Phone (217) 782-2113
Certified Mail No: 7016 3560 0000 7695 4731
(Two Copies)

Illinois Environmental Protection Agency
412 SW Washington St., Suite D
Peoria, IL 61602
Phone (309) 693-5463
Certified Mail No: 7016 3560 0000 7695 4724
(One Copy)

RE: Semi-Annual Compliance Report – Subpart VVa
Adkins Energy, LLC
4350 West Galena Road
Lena, IL 61048
Site ID No: 177802AAA
FESOP Permit No: 03060057
Construction Permit No: 13080015

Dear Sir/Madam:

Please find enclosed two (2) copies of the semi-annual compliance report for the first six months (January through June) of 2019, provided by Montrose. This report is being submitted pursuant to 40 CFR 60.487a (c) and Special Condition 2.4.9 of the above referenced construction permit.

If you have any questions or need any additional information, please do not hesitate to contact me at 815-369-9173.

Sincerely,

Christopher L. Posey, CHMM
Environmental and Safety Manager

Enclosure



Adkins Energy
4350 W Galena Road
Lena, IL 61048

Report Period 01/01/2019 - 06/30/2019

Process Unit: PLANT

Monitoring Program: NSPS-VVA

SEMIANNUAL SUMMARY REPORT

LEAK REPORT

	01/01/2019 - 01/31/2019 (114 In Unit)	02/01/2019 - 02/29/2019 (117 In Unit)	03/01/2019 - 03/31/2019 (117 In Unit)	04/01/2019 - 04/30/2019 (117 In Unit)	05/01/2019 - 05/31/2019 (117 In Unit)	06/01/2019 - 06/30/2019 (117 In Unit)
Valves						
Monitored	117	3	0	117	0	0
Leaks Detected	0	0	0	0	0	0
Leaks Not Reaired within 15 Days	0	0	0	0	0	0
Pumps						
Monitored	2	2	2	2	2	2
Leaks Detected	0	0	0	0	0	0
Leaks Not Reaired within 15 Days	0	0	0	0	0	0

EQUIPMENT COUNTS

	Beginning Counts	Added	Removed	Ending Counts
Valves	114	3	0	117
Pumps	3	0	0	3

Total Components Beginning of Reporting Period:	117	Total Components Added:	3
Total Components End of Reporting Period:	120	Total Components Deleted:	0
Total Components Monitored:	119	Total Monitoring Events:	249
Total Leaks:	0	Total Leaks Not Reaired within 15 Days:	0



Adkins Energy
4350 W Galena Road
Lena, IL 61048

Report Period 01/01/2019 - 06/30/2019

Process Unit: BIODIESEL

Monitoring Program: NSPS-VVA

SEMIANNUAL SUMMARY REPORT

LEAK REPORT

	01/01/2019 - 01/31/2019 (356 In Unit)	02/01/2019 - 02/29/2019 (356 In Unit)	03/01/2019 - 03/31/2019 (356 In Unit)	04/01/2019 - 04/30/2019 (356 In Unit)	05/01/2019 - 05/31/2019 (356 In Unit)	06/01/2019 - 06/30/2019 (356 In Unit)
Valves						
Monitored	321	0	30	321	5	0
Leaks Detected	0	0	0	0	0	0
Leaks Not Reaired within 15 Days	0	0	0	0	0	0
Pumps						
Monitored	20	20	20	20	20	20
Leaks Detected	0	0	0	0	0	0
Leaks Not Reaired within 15 Days	0	0	0	0	0	0

EQUIPMENT COUNTS

	Beginning Counts	Added	Removed	Ending Counts
Valves	356	0	0	356
Pumps	21	0	0	21

Total Components Beginning of Reporting Period:	377	Total Components Added:	0
Total Components End of Reporting Period:	377	Total Components Deleted:	0
Total Components Monitored:	376	Total Monitoring Events:	797
Total Leaks:	0	Total Leaks Not Reaired within 15 Days:	0